Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page <u>1</u> of <u>1</u>
PATENT NO. : 7,111,522
APPLICATION NO.: 10/788,745
ISSUE DATE : 09/26/2006
INVENTOR(S) : Wingett, et al.
It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:
Column 10, line 15, "outer side; and" should be changed toouter side, and; Column 11, line 41, "end," should be changed toends,; Column 11, line 47, "tat" should be changed tothat

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Ingrassia Fisher & Lorenz 7150 E. Camelback Rd., Suite 325 Scottsdale, Arizona 85251

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U. S. Patent: 7,111,522 Examiner: R. Pang

Issued: 9/26/2006 Group: 3681

Inventor(s): Wingett, et al. Docket No. H0005310

For: ENERGY STORAGE FLYWHEEL SYSTEM CONTAINMENT VESSEL

CERTIFICATE OF CORRECTION UNDER 37 CFR 1.322

Attn: Certificate of Corrections Branch

P.O. Box 1450

Alexandria, VA 22313-1450

Sir:

Please correct the above-identified patent by issuing a Certificate of Correction for a Patent Office mistake under Rule 1.322 as follows:

Column 10, line 15, "outer side; and" should be changed to --outer side, and--;

Column 11, line 41, "end," should be changed to --ends,--;

Column 11, line 47, "tat" should be changed to --that--.

These errors occurred through the fault of the Patent Office and no fee is involved. The issuance of a Certificate of Correction under Rule 1.322 is therefore considered proper.

Respectfully submitted,

Date: April 12, 2007

Ingrassia Fisher & Lorenz, P.C.

/PAUL D. AMROZOWICZ/

By: Paul D. Amrozowicz Attorney for Applicant(s)

Reg. No. 45,264 Tel. (480) 385-5060 Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

OLIVIII IO/VIE OI OOIVILOIION			
	Page <u>1</u> of _	1	
PATENT NO. : 7,111,522	J =		
APPLICATION NO.: 10/788,745			
ISSUE DATE : 09/26/2006			
INVENTOR(S) : Wingett et al.			
It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:			
Column 11, line 8, "having in inner" should be changed tohaving an inner; Column 11, line 48, "coupled to outer" should be changed tocoupled to the outer			

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Ingrassia Fisher & Lorenz 7150 E. Camelback Rd., Suite 325 Scottsdale, Arizona 85251

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U. S. Patent: 7,111,522 Examiner: R. Pang

Issued: 9/26/2006 Group: 3681

Inventor(s): Wingett, et al. Docket No. H0005310

For: ENERGY STORAGE FLYWHEEL SYSTEM CONTAINMENT VESSEL

CERTIFICATE OF CORRECTION UNDER 37 CFR 1.323

Certificate of Corrections Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

Please correct the above-identified patent by issuing a Certificate of Correction for Applicant's mistake under Rule 1.323 as follows:

Column 11, line 8, "having in inner" should be changed to --having an inner--; Column 11, line 48, "coupled to outer" should be changed to --coupled to the outer--.

The above errors were made unintentionally. You are hereby authorized to charge our Deposit Account No. 50-2091 \$100.00 per Rule 1.20(a), and any other fee deemed necessary:

Respectfully submitted,

Date: April 12, 2007 /PAUL D. AMROZOWICZ/

Ingrassia Fisher & Lorenz, P.C.

By: Paul D. Amrozowicz
Attorney for Applicant(s)

Reg. No. 45,264 Tel. (480) 385-5060